

Window Assessment--Interior

Date:

Project:

Client:



Location:

W 201

Window Description:

Stool: MESSML

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip HORIZONTAL SURFACES
- Repair
- Replace (RAILS)

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails: RIGHT INT, TRIM
IS SCRIBED TO BRICK

Hardware Description:

STEEL MOETISE PULLEY

- Strip PULLEYS
- Missing L + L

Ropes/Chains MISSING

- Replace 4 ROPES NEEDED

Remarks:

Weatherstripping: 7/9

Window Assessment--Interior

Date:

Project:

Client:

	Location: <u>W202</u>
	Window Description: <u>DH w/ TRANSOM</u>
	Stool: <u>MISSING</u> <input type="checkbox"/> Strip <input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replace
	Frame/Pulley Stiles: <u>FAIR</u> <input checked="" type="checkbox"/> Strip <u>REFINISH</u> <input type="checkbox"/> Repair <input type="checkbox"/> Replace
	Sash/Muntins/Leading: <u>FAIR</u> <input checked="" type="checkbox"/> Strip <u>HORIZONTAL SURFACES</u> <input type="checkbox"/> Repair <input type="checkbox"/> Replace
	Trim: <u>FAIR</u> <input type="checkbox"/> Strip <input checked="" type="checkbox"/> Repair <u>REFINISH</u> <input type="checkbox"/> Replace
ails:	Hardware Description: <u>STEEL MORTISE PULLEY</u> <input checked="" type="checkbox"/> Strip <u>PULLEY</u> <input checked="" type="checkbox"/> Missing <u>LOCK+LIFT</u>
Remarks:	Ropes/Chains: <u>4X</u> <input checked="" type="checkbox"/> Replace
	Weatherstripping: <u>n/a</u>

Window Assessment--Interior

Date:

Project:

Client:



Location:

W203

Window Description:

OH W/TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip + REFINISH
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip HORIZONTAL RAILS
- Repair BAR JOINERY
- Replace HAS SEPERATED

Trim: FAIR

- Strip APPLY
- Repair SEALANTS
- Replace AT MASONRY

ails:

Hardware Description:

PULLEY

- Strip PULLEYS
- Missing LTL

Ropes/Chains

- Replace 4X

Remarks:

Weatherstripping:

n/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W204

Window Description:

DH W/TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip RAILS + BARS
- Repair
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

Hardware Description:

PULLEY

- Strip PULLEYS
- Missing LOCK + LIFT

Ropes/Chains

4X

- Replace

ails: UPPER SASH HAS DROPPED
 @ LEFT CORNER.

Remarks:

Weatherstripping:

n/A

Window Assessment--Interior

Date:

Project:

Client:

	Location: W 205
	Window Description: DH w/TRANSOM
	Stool: MISSING <input type="checkbox"/> Strip <input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replace
	Frame/Pulley Stiles: FAIR <input checked="" type="checkbox"/> Strip <input type="checkbox"/> Repair <input type="checkbox"/> Replace
	Sash/Muntins/Leading: FAIR <input checked="" type="checkbox"/> Strip RAILS + BARS <input checked="" type="checkbox"/> Repair TRANSOM + <input type="checkbox"/> Replace MEETING RAIL
	Trim: <input type="checkbox"/> Strip <input checked="" type="checkbox"/> Repair PAINT <input type="checkbox"/> Replace
	Hardware Description: PULLEY <input checked="" type="checkbox"/> Strip PULLEY <input checked="" type="checkbox"/> Missing LOCK + LIFT
Remarks:	Ropes/Chains <input checked="" type="checkbox"/> Replace 4x
Remarks:	Weatherstripping:

Window Assessment--Interior

Date:

Project:

Client:

→ SAME AS 205



Location:

W206

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip **RAILS + BARS**
- Repair **MTNG RAIL, LWR RAIL**
- Replace

Trim:

- Strip
- Repair **PAINT**
- Replace

ails:

UV DAMAGE ON HORIZONTAL LOCATIONS

Hardware Description:

PULLEY

- Strip **PULLEY**
- Missing **LOCK + LIFT**

Ropes/Chains

- Replace

4X

Remarks:

Weatherstripping:

n/a

Window Assessment--Interior

Date:

Project:

Client:



Location:

W207

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading:

- Strip LOWER RAIL
- Repair BARS + LOWER RAIL
- Replace LOOSE JOINERY

Trim:

- Strip
- Repair SURFACE DAMAGE IN UPPER ARCH CASING
- Replace

ails:

Hardware Description:

- PULLEY
- Strip PULLEY
- Missing LOCK UP

Ropes/Chains

- Replace 4 X

Remarks:


Weatherstripping: n/a

Window Assessment--Interior

Date:

Project:

Client:



Location:

W208

Window Description:

DM W/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip RAILS + BARS
- Repair LOOSE JOINERY
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

PULLEY

- Strip PULLEY
- Missing LOCK + LIFT

Ropes/Chains

- Replace 4x

Remarks:

Weatherstripping:

N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W209

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace PARTING BEAD

Sash/Muntins/Leading: FAIR

- Strip RAILS + BARS
- Repair BARS
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

PULLEY

- Strip PULLEY
- Missing LOCK LIFT

Ropes Chains

- Replace 4x

Remarks:


Weatherstripping: N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W 210

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace (R) POCKET DOOR

Sash/Muntins/Leading: FAIR

- Strip RAILS + BARS
- Repair JOINERY
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

PULLEY

- Strip PULLEY
- Missing LOCK + LIG

Copes/Chains

- Replace 4X

Remarks:

Weatherstripping: n/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W211

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip SASH
- Repair LOWER RAIL
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

- Strip PULLEY
- Missing LOCK BOLT

Ropes/Chains

- Replace 4X

Remarks:

Weatherstripping:


N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W212

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntin/Leading: FAIR

- Strip DAMAGE @ JOINT
- Repair @ JOINT
- Replace

Trim: FAIR

- Strip
- Repair ARCH CASING
- Replace INT. STOP

Hardware Description:

PULLEY

- Strip PULLEY
- Missing LOCK + LIFT

Ropes/Chains

- Replace 4X

ails: PREVIOUS REPAIRS @
LOWER RAIL PERFORMED
POORLY

Remarks:

Weatherstripping: N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W213

Window Description:

DN w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace PARTING BEAD

Sash/Muntins/Leading: FAIR

- Strip RAILS + BARS
- Repair JOINERY
- Replace

Trim: FAIR

- Strip
- Repair
- Replace INT. STOP

Hardware Description:

- PULLEY
- Strip PULLEY
- Missing LOCK + LIFT

Ropes/Chains

- Replace 4X

ails: UPPER SASH HAS DROPPED AND VOID HAS BEEN FILLED WITH SEALANT

Remarks:

Weatherstripping: N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

WZ14

Window Description:

DH w/TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip RAILS + BARS
- Repair LOOSE JOINERY
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace PARTING BEAD

ails:

Hardware Description:

PULLEY

- Strip PULLEY
- Missing LOCK LIFT

Ropes/Cains

4x
 Replace

Remarks:

Weatherstripping: n/a

Window Assessment--Interior

Date:

Project:

Client: SAME AS 206



Location:

W215

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip BARS + TRAILS
- Repair
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

PULLEY

- Strip PULLEY
- Missing STRIKE IS PRESENT

Ropes/Chains

- Replace 4X

Remarks:

Weatherstripping: n/A

Window Assessment--Interior

Date:

Project:

Client:

	Location: <u>W216</u>
	Window Description: <u>DH w/ TRANSOM</u>
	Stool: <u>MISSING</u> <input type="checkbox"/> Strip <input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replace
	Frame/Pulley Stiles: <u>FAIR</u> <input checked="" type="checkbox"/> Strip <input type="checkbox"/> Repair <input type="checkbox"/> Replace
	Sash/Muntins/Leading: <u>FAIR</u> <input checked="" type="checkbox"/> Strip <u>SASH</u> <input checked="" type="checkbox"/> Repair <u>TRANSOM TOPRAIL</u> <input type="checkbox"/> Replace
	Trim: <u>FAIR</u> <input type="checkbox"/> Strip <input checked="" type="checkbox"/> Repair <u>PAINT</u> <input type="checkbox"/> Replace
	Hardware Description: <u>PULLEY</u> <input checked="" type="checkbox"/> Strip <u>PULLEY</u> <input checked="" type="checkbox"/> Missing <u>SPRINGS IS PRESENT</u>
Remarks:	Rope/Chains: <u>4x</u> <input checked="" type="checkbox"/> Replace
Remarks:	Weatherstripping: <u>n/a</u>

Window Assessment--Interior

Date:

Project:

Client:

	Location: W217
	Window Description: DH w/ TRANSOM
	Stool: MISSING <input type="checkbox"/> Strip <input type="checkbox"/> Repair <input checked="" type="checkbox"/> Replace
	Frame/Pulley Stiles: FAIR <input checked="" type="checkbox"/> Strip <input type="checkbox"/> Repair <input type="checkbox"/> Replace
	Sash/Muntins/Leading: <input checked="" type="checkbox"/> Strip BARS + RAJUS <input checked="" type="checkbox"/> Repair TRANSOM <input type="checkbox"/> Replace
	Trim: FAIR <input type="checkbox"/> Strip <input checked="" type="checkbox"/> Repair PAINT <input type="checkbox"/> Replace
	Hardware Description: PULLEY <input checked="" type="checkbox"/> Strip PULLEY <input checked="" type="checkbox"/> Missing LOCK + LIFT
Remarks:	Rope/Chains: 4x <input checked="" type="checkbox"/> Replace Weatherstripping: N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W 218

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip BARSTRAILS
- Repair
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace PARTING BEAD

ails:

Hardware Description:

- PULLEY
- Strip PULLEY
- Missing WORK + LIFT

Ropes/Chains

- Replace 4X

Remarks:

Weatherstripping: N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W 219

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: CRITICAL

- Strip UPPER IS CRITICAL
- Repair CRITICAL
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

PULLEY
 Strip PULLEY
 Missing LOCK + LIFT

Ropes/Chains

- Replace 4x

Remarks:

Weatherstripping: N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W220

Window Description:

DH w/ Transom

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip BARS + RAILS
- Repair UPPER SASH
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace PARTING-BEAD + INT. SQP

ails:

Hardware Description:

- PULLEY
- Strip PULLEY
 - Missing LOCKUP

Ropes/Chains

- Replace 4x

Remarks:

Weatherstripping: n/a

Window Assessment--Interior

Date:

Project:

Client:



Location:

W 221

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip **BARSTAILS**
- Repair
- Replace

Trim: FAIR

- Strip
- Repair **PAINT**
- Replace **PARTING BEAD**

ails:

Hardware Description:

PULLEY

- Strip **PULLEY**
- Missing **LOCK+LIFT**

Ropes/Chains

- Replace **4X**

Remarks:

Weatherstripping:


w/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W 222

Window Description:

DH w/ TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading:

- Strip
- Repair PROFILE JOINERY TRANSOM
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

- PULLEY
- Strip PULLEY
- Missing LATCH IS PRESENT

Ropes/Chains

- Replace 4X

Remarks:

Weatherstripping: N/A

Window Assessment--Interior

Date:

Project:

Client:



Location:

W108

Window Description:

MULLED DR W/TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip + REFINISH
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip + REFINISH
- Repair TRANSOM
- Replace UPPER (R) RAIL

Trim: FAIR

- Strip
- Repair SEALANTS
- Replace INT. STOP

~~RECOMMEND INT. STOP INSTALLATION~~

ails:

- PROFILES ARE 25%
DAMAGED

Hardware Description:

PULLEY

- Strip LOCKSTAPLES
- Missing LIFTS

Ropes/Chains

- Replace

2X

Remarks:

Weatherstripping: n/a

Window Assessment--Interior

Date:

Project:

Client:



MISSING SPOKE MUNTIN

ails:

Location:

W109

Window Description:

MULLED DH w/TRANSOM

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip SASH
- Repair MUNTIN
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

Hardware Description:

PULLEYS + LOCKS

- Strip PULLEYS + LOCKS
- Missing

Ropes/Chains

- Replace 3X

Remarks:

Weatherstripping: 1/A

Window Assessment--Interior

Date:

Project:

Client:

108
SAME AS



Location:

W110

Window Description:

KNULLED DM w/TRANSON

Stool: MISSING

- Strip
- Repair
- Replace

Frame/Pulley Stiles: FAIR

- Strip
- Repair
- Replace

Sash/Muntins/Leading: FAIR

- Strip SASH
- Repair MUNTINS/MTNS RAIL
- Replace

Trim: FAIR

- Strip
- Repair PAINT
- Replace

ails:

Hardware Description:

PULLEY + LOCK

- Strip
- Missing

Ropes/Chains

- Replace

OK

Remarks:

Weatherstripping:

n/a

Window Assessment--Interior

Date:

Project:

Client:



Location:

W111

Window Description:

MULLED DU W/TRANSOM

Stool: MISSING

Strip

Repair

Replace

Frame/Pulley Stiles: FAIR

Strip

Repair

Replace

Sash/Muntins/Leading: POOR

Strip

Repair 60%

Replace OR NEED WORK

Trim: FAIR

Strip

Repair PAINT

Replace

Hardware Description:

PULLEY + LOCK

Strip

Missing

Ropes/Chains

Replace BX

ails: MUNTINS ARE IN POOR CONDITION.
STILES ARE IN POOR CONDITION.
BARS + LOWER RAILES ARE IN FAIR CONDITION

Remarks: REPLACEMENT PARTS

Weatherstripping: n/a

